

● good ● moderate ● sensitive ● unhealthy  
● very unhealthy ● hazardous

Exceedances	0
Exceeded Time	0%
Alarm Condition	N/A

good: < 10

moderate: < 20

sensitive: < 50

unhealthy: < 100

very unhealthy: < 200

hazardous: < 300

Connected Events

Date & Time	Type	Notes	Justification	Occurances
-------------	------	-------	---------------	------------

# Sensor Report

Sulfur Dioxide

SENSOR ID: 5562, Facility: Murphy

Equipment ID: SL052302





**SL052302**  
Future of Sensory Technology

Equip. Name: SL052302

Last Calibration: N/A

Report Generated: 2024.10.15

Report Date: 2024.10.07 00:00 - 2024.10.14 00:00



● good ● moderate ● sensitive ● unhealthy  
● very unhealthy ● hazardous

Exceedances	0
Exceeded Time	0%
Alarm Condition	N/A

good: < 35

moderate: < 75

sensitive: < 185

unhealthy: < 304

very unhealthy: < 604

hazardous: < 1004

## Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

# Sensor Report

Total VOC - PID

**SENSOR ID: 5569, Facility: Murphy**

Equipment ID: SL052302



**SL052302**  
Future of Sensory Technology

Equip. Name: SL052302



Report Date: 2024.10.07 00:00 - 2024.10.14 00:00

Last Calibration: N/A

Report Generated: 2024.10.15



Data Trend Shows 0



● good ● moderate ● sensitive ● unhealthy  
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

good: < 50

moderate: < 100

sensitive: < 150

unhealthy: < 200

very unhealthy: < 300

hazardous: < 500

## Connected Events

Date & Time

Type

Notes

Justification

Occurrences

# Sensor Report

Sound Intensity Level - Class II

SENSOR ID: 5595, Facility: Murphy

Equipment ID: SL052302





Equip. Name: SL052302



Last Calibration: N/A

Report Generated: 2024.10.15

Report Date: 2024.10.07 00:00 - 2024.10.14 00:00





Data Trend Shows No Significant Trend →





Exceedances	0
Exceeded Time	0%
Alarm Condition	N/A

## Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------



Data Trend Shows No Significant Trend →



- good
- moderate
- sensitive
- unhealthy
- very unhealthy
- hazardous

Exceedances	0
Exceeded Time	0%
Alarm Condition	N/A



Connected Events

Date & Time	Type	Notes	Justification	Occurances
-------------	------	-------	---------------	------------

# Sensor Report

Sulfur Dioxide

SENSOR ID: 5549, Facility: Murphy

Equipment ID: SL052301



**SL052301**  
Future of Sensory Technology

Equip. Name: SL052301




Report Date: 2024.10.07 00:00 - 2024.10.14 00:00

Last Calibration: N/A

Report Generated: 2024.10.15



Data Trend Shows No Significant Trend →



● good ● moderate ● sensitive ● unhealthy  
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

good: < 35

moderate: < 75

sensitive: < 185

unhealthy: < 304

very unhealthy: < 604

hazardous: < 1004

## Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

# Sensor Report

Total VOC - PID

SENSOR ID: 5556, Facility: Murphy

Equipment ID: SL052301





**SL052301**  
Future of Sensory Technology

Equip. Name: SL052301

Last Calibration: N/A

Report Generated: 2024.10.15

Report Date: 2024.10.07 00:00 - 2024.10.14 00:00



● good ● moderate ● sensitive ● unhealthy  
● very unhealthy ● hazardous

Exceedances	0
Exceeded Time	0%
Alarm Condition	N/A

good: < 50	moderate: < 100	sensitive: < 150	unhealthy: < 200	very unhealthy: < 300	hazardous: < 500
------------	-----------------	------------------	------------------	-----------------------	------------------

## Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

# Sensor Report

Sound Intensity Level - Class II

SENSOR ID: 5594, Facility: Murphy

Equipment ID: SL052301






Equip. Name: SL052301

Report Date: 2024.10.07 00:00 - 2024.10.14 00:00

Last Calibration: N/A

Report Generated: 2024.10.15



Exceedances	0
Exceeded Time	0%
Alarm Condition	N/A

## Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------